

Introduction

The purpose of this notice is to make all Customers aware of an update to a Package Guidance Document (PAA GN03) and the introduction of two new Package Guidance Documents (PAA GN17 and PAA GN18), associated with addressing damaged (customer owned) LLWR IP-2 ISO Containers.

Container Repair Guidance

In summary, many traditional repair methods for LLWR IP-2 ISO Containers are no longer deemed acceptable under the conditions of the new LLWR Environmental Safety Case (ESC) for disposal into the vault. The following Package Guidance Documents have been amended/prepared to address this change:

- Revised - PAA GN03 – IP-2 ISO Container Stud Repair Guide (Issue 2) – Guidance for the repair of sheared lid clamp studs on the LLWR Type IP-2 ISO freight containers.
- New - PAA GN17 – IP-2 ISO Punctured Container Repair Guide (Issue 1) - Guidance for Conditioning of Punctured Containers (loaded with LLW) for onward transport to the LLWR vaults in IP-2 licensed over containers.
- New - PAA GN18 – IP-2 ISO Container Surface Paint Repair Guide (Issue 1) – Guidance for carrying out minor paint repairs on the external surfaces of LLWR Type IP-2 ISO Freight Containers.

The above documents are now available for download from the LLWR Website at www.llwrsite.com/customer-portal/packaging

Further Information and Questions

If you require any further information or have any queries relating to this Customer Notice, please send an e-mail to: transportandlogistics@llwrsite.com or call 019467 70301

Distribution List

We have issued this Notice to the following people from your Company's Contact Details Form (Reference: WSC-FOR-CON):

- All nominated representatives

If you need to update these details, please submit a revised Form: <http://llwrsite.com/customer-portal/resources/>