

Introduction

This notice is intended to provide guidance to all consignors, consignees and operators of LLWR Approved IP-2 Containers, in particular operators of TC01, TC03 Containers and TC03 Overlids.

Stacking of TC01 & TC03 Containers

It has been brought to our attention that a number of TC01 and TC03 containers have suffered damage and need repaired as a result of improper stacking operations. The design of all LLWR disposal containers TC01 and TC03 have lid designs which sit proud of the top corner castings and therefore all need to be stacked using stacking cones for interim storage operations or locking stacking blocks for transport. This is to ensure the lid of the lower container does not interfere with the base of the upper container. Further details can be found in the Packing and Handling Instructions for each package design. LLWR offer a supply of compliant stacking cones for interim storage operations, if required, please request supply via E-Logistics enquiry process.

TC03 Securing Overlids

All TC03 containers are required to be transported using a specific TC03 Overlid. This is to prevent the recessed lid from retaining water during transport. TC03 Overlids must be secured to the TC03 container in accordance with the TC03 Packing and Handling instructions reference OM_0102940_MECH_00001_F, section 8.3.3; *“For container variants that utilise an overlid, the overlid should be fitted and secured using four shear pins to the correct specification. Spare shear pins must be obtained from the Contract Authority if required”*. LLWR offer a supply of compliant “Shear Pins” please request supplies via E-Logistics enquiry process.

TC03 Overlid location survey

Due to the lack of customer demand of the TC03 containers, the manufacture of additional Overlids is on hold until LLWR decides on the future of the TC03 container. LLWR TC03 Overlid stock is diminishing due to fatigue. LLWR requests customers feedback regarding the number of TC03 Overlids they have stored on their site. In order for LLWR to maintain their existing stock it may be necessary to recall Overlids for refurbishment and redistribution to support short term demand to all users of TC03 containers.

Please circulate this information to all relevant personnel within your organisation.

Further Information

If you would like any further information or have any questions please do get in touch with our Transport and Logistics Team by e-mail: transportandlogistics@llwrsite.com or by phone: 019467 70301.

Distribution List

We have issued this Notice to the following people from your Company's Contact Details Form (Reference: WSC-FOR-CON):

- All nominated representatives
- [Insert Role Titles as required]

If you need to update these details, please submit a revised Form: <http://www.llwrsite.com/customers/customer-forms>